

General Environmental Incident Summary

Incident: 1779 **Notice:** 8/2/2012 0800 **Occurred:** 7/31/2012 1730
DEM Incident No: **No Further Action:** ☒
Responsible Party: John
County: Burleigh
Twp Rng Sec Qtr: 138 80 7
Lat Long + Method: 46.78636 -100.82690 Derived from TRS
Location Description: 24 ft Bayliner sink at Southport Marina
Submitted By Info: Al Hunt
NDDoH Response Team
918 E Divide Ave
4th Floor
Bismarck ND 58501-1947
Received By Info:
Contact Info: John Unruk
Unruk
Bismarck ND
Affected Medium: 02 - water
Near. Occupied Bldg: 100 Feet
Type of Incident: Boat sink
Release Contained:
Reported to NRC: Unknown
Contaminant: Diesel
Volume of Release:
Duration of Release:
Agriculture Related: No
EPA Extremely Hazardous Substance: Unknown
Number of Fatalities:
Number of Injuries:
Cause of Incident:
A 24 ft Bayliner sunk at dock at Southport Marina
Risk Evaluation:
Potential Env. Impacts:
Action Taken/Planned:
Wastes Disposal Location:
Other Agencies Involved:

Updates

Date: 8/2/2012 ***Status:*** Inspection

Author: Hunt, Al

Notes:

Walked site with Carl along the docks and Causeway. No sheen was seen on the water. A little bio-sheen, but not gas or diesel. Talked with Marina owner, Dave Moritz, he stated that boat sank late on 7-31-2012. Was pulled from water at Marina dock on 8-1-2012.

Updated Volume: None at the time of this update